DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: 1sb@dhw.idaho.qov

June 23, 2010

RICHARD M. ARMSTRONG - Director

Ferren Weeks, Administrator Yellowstone Group Home #2 (Sunnybrook) 560 West Sunnyside Lane Idaho Falls, Idaho 83401

RE: Yellowstone Group Home #2 (Sunnybrook), Provider #13G064

Dear Mr. Weeks:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Yellowstone Group Home #2 Sunnybrook, on June 15, 2010.

Enclosed is a Statement of Deficiencies/Plan of Correction, Form CMS-2567, listing Medicaid deficiencies and a similar form listing State licensure deficiencies. In the spaces provided on the right side of each sheet, please provide a Plan of Correction. <u>It is important</u> that your Plan of Correction address each deficiency in the following manner:

- 1. What corrective action(s) will be accomplished for those individuals found to have been affected by the deficient practice;
- 2. How you will identify other individuals having the potential to be affected by the same deficient practice and what corrective action(s) will be taken;
- 3. What measures will be put in place or what systemic change you will make to ensure that the deficient practice does not recur;
- 4. How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place; and,
- 5. Include dates when corrective action will be completed. 42 CFR 488.28 states ordinarily a provider is expected to take the steps needed to achieve compliance

FerrenWeeks, Administrator June 23, 2010 Page 2 of 2

within 60 days of being notified of the deficiencies. Please keep this in mind when preparing your plan of correction. For corrective actions which require construction, competitive bidding, or other issues beyond the control of the facility, additional time may be granted.

Sign and date the form(s) in the space provided at the bottom of the first page.

After you have completed your Plan of Correction, return the original to this office by **July 6, 2010**, and keep a copy for your records.

Thank you for the courtesies extended to us during our visit. If you have any questions, please call or write this office at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Health Facility Surveyor

Juph Bu

Fire Life Safety & Construction Program

TB/lj

Enclosure

Printed: 06/23/2010

DEPARTM	ENT OF HEALTH FOR MEDICARE	AND HUMAN SERV & MEDICAID SERV	ICES				M APPROVED D. 0938-0391
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		MBER:	(X2) MULTIPLE CONSTRUCTION A BUILDING 02 B. WING		(X3) DATE: COMPL		
		13G064				06/	15/2010
	VIDER OR SUPPLIER	0115 40 (0) 1111 (0)			TATE, ZIP CODE		
YELLOWS	TONE GROUP H	OME #2 (SUNNYBR		JNNYBRO FALLS, ID		,	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENC: MUST BE PRECEEDED B LSC IDENTIFYING INFORM	Y FULL	ID PREFIX TAG	(EACH CORRECT CROSS-REFERENC	LAN OF CORRECTION IVE ACTION SHOULD BE ED TO THE APPROPRIATE FICIENCY)	(X6) COMPLETION DATE
K 000 IN	IITIAL COMMENT	rs		K 000			
cc R al bi it	onstruction. It is for esponse sprinkler arm/smoke detect uilt/completed on It is licensed for 6 K the following deficit	gle story, type V(000) ully sprinklered with (heads. It has a contion system. This ho February 23, 1998. (CF/MR beds. encies were cited at hual Fire/Life Safety	Quick hplete fire me was Currently		Please Plan o	su attacli f lorried A gw	ten
E co	onducted on June prveyed under the dition, Chapter 33	15, 2010. The facilit LIFE SAFETY COD , Existing Residentia cies, adopted 11 Mar	y was E, 2000 I Board				27 (2)
: Ti by		safety survey was co	nducted				The same broken is
į H	aylor Barkley ealth Facility Surv ecility Fire Safety a			:			:
	33.470(j)(1)(i) LIFE FANDARD	SAFETY CODE	i.	K0046			
	illities comply with 3.2.5.1	Section 9.1. 32.2.	5.1,				
Ba fa Se	ased on observation	ot met as evidenced lon it was determined ure that utilities comp tility had a census of	that the lied with				
CII	ents on the day of	i ure survey.					

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Any deliciency stitement ending with a asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

88SK21

If continuation sheet Page 1 of 4

DEPARTMENT OF HEALTH AND HUMAN SERVICES CERTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 06/23/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIE IDENTIFICATION NUM		BER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING		(X3) DATE SURVEY COMPLETED		
_		13G064			A ST	06/	15/2010
	ROVIDER OR SUPPLIER	OME #0 (CHAINVDD		RESS, CITY. S' JNNYBROK	TATE, ZIP CODE		
TELLOV	VSTONE GROUP II	OME #2 (SUNNYBR		FALLS, ID			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIE Y MUST BE PRECEEDED B' LSC IDENTIFYING INFORM	Y FULL	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE AC CROSS-REFERENCED TD DEFICIEN	TION SHOULD BE THE APPROPRIATE	COMPLETION DATE
K0046	Continued From pa	age 1		K0046			
	During the facility to AM, observation of multiple electrical a noted by the Surve Maintenance Mana	ger. This deficiency a present on the day of	a gs were				
 		d equipment shall be FPA 70, National Elec		· 			7. C
K0154	out of service for m period, the authority notified, and the but approved fire watch parties left unproted	utomatic sprinkler sylore than 4 hours in a having jurisdiction silding shall be evacual system be provided the down the shutdown sheen returned to se	24-hour hall be ited or an for all until the	K0154			
	Based on record ret the facility did not he facility in the event of	ot met as evidenced to view it was determine ave a fire watch polici of a sprinkler system ensus of five clients o	ed that y for the failure.				

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 06/23/2010 FORM APPROVED OMB NO. 0938-0391

AND PLAN OF CORRECTION IDENTIFICATION		(X1) PROVIDER/SUPPLIES IDENTIFICATION NUMBER 13G064	MBER: A. BUILDING 02			(X3) DATE SURVEY COMPLETED 06/15/2010	
	ROVIDER OR SUPPLIER	OME #2 (SUNNYBR	STREET ADD	PRESS, CITY, S UNNYBROG FALLS, ID		06/	15/2010
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIE / MUST BE PRECEEDEO B' LSC IDENTIFYING INFORM	Y FULL	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE AC CROSS-REFERENCED TO DEFICIEN	TION SHOULD BE THE APPROPRIATE	(X5) COMPLETION DATE
K0154	plans on June 15, 2 determined that the watch policy in the t the Surveyor and th Manager. This defice	_	vas a fire e noted by ce	K0154			
İ	service for more that the authority having and the building sha approved fire watch shall be prov	re alarm system is ou an 4 hours in a 24-ho jurisdiction shall be i all be evacuated or ar ided for all parties lef shutdown until the fire	ur period, notified, n	K0155			
	Based on record retthe facility did not be facility in the event of the facility had a ce of the survey. The findings include During record review plans on June 15, 2 determined that the watch policy in the findings in the findings in the findings are policy in the findings are considered.	w of the facility's eme 010 at 10:59 AM, it w facility did not have a acility. Findings were	rgency ras a fire noted by				
		e Facility Maintenand iency affected all stat		!			

p.6

Printed: 06/23/2010 FORM APPROVED OMB NO. 0938-0391

DEPART	MENT OF HEALTH	AND HUMAN SERV & MEDICAID SERVI	ICES			FORM OMB NO	M APPROVED D. 0938-0391
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		13G064		B WING		06/1	15/2010
	ROVIDER OR SUPPLIER				TATE, ZIP CODE		
YELLOV	VSTONE GROUP H	OME #2 (SUNNYBR		UNNYBRO			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIS Y MUST BE PRECEEDED 3 LSC IDENTIFYING INFORM	Y FULL	PREFIX TAG	PROVIDER'S PLAN O (EACH CORRECTIVE AS CROSS-REFERENCED TO DEFICIEN	CTION SHOULO BE THE APPROPRIATE	(XE) COMPLETION DATE
K0155	Continued From pa	age 3 he day of the survey.		K0155			
			Ì				
	ļ		1				
							· · · · · · · · · · · · · · · · · · ·
							.;
				j			
				İ			
ORM CMS.	2567(02-99) Previous Ve	rsions Obsolete			88\$K21	If continuation	sheet Page 4 of

Yellowstone Group Homes

p.7 PRINTED: 06/22/2010

FORM APPROVED

Bureau of Facility Standards STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING B. WING 06/15/2010 13G064 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 3245 SUNNYBROOK LANE YELLOWSTONE GROUP HOME #2 (SUNNYBROOK IDAHO FALLS, ID 83404 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) M 000 16.03.11 Inital Comments M 000 The facility is a single story, type V(000) construction. It is fully sprinklered with Quick Response sprinkler heads. It has a complete fire alarm/smoke detection system. This home was built/completed on February 23, 1998. Currently it is licensed for 6 ICF/MR beds. The following deficiencies were cited at the above facility during the annual Fire/Life Safety survey conducted on June 15, 2010. The facility was surveyed under the LIFE SAFETY CODE, 1976 Edition, "Lodging and Rooming Houses" contained in Chapter 11, "Lodging and Rooming House Occupancies " and applicable provisions of Chapters 01 through 07, Chapter 17 and Appendices A and B of the Life Safety Code, Impractical Evacuation Capability in accordance with IDAPA 16.03.11. The annual fire/life safety survey was conducted Taylor Barkley Health Facility Surveyor Facility Fire Safety and Construction MM309 16.03.11.110 Fire and Life Safety Standards MM309 Buildings on the premises used as facilities must meet all the requirements of local, state and national codes concerning fire and life safety standards that are applicable to ICF/MR facilities. This Rule is not met as evidenced by: Refer to federal deficiencies listed on the CMS 2567 form. K0154 Fire watch policy for sprinkler system failure. LABORATORY DIRECTOR'S OR PROVIDER/SMPPLIER REPRESENTATIVE'S SIGNATURE (X6) DATE agional administrator STATE FORM If continuation sheet 1 of 2

PRINTED: 06/22/2010 FORM APPROVED

	Facility Standards		-,				
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIE IDENTIFICATION NUM			(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
13G064			B. WING_		06/15/2010		
					STATE, ZIP CODE		
YELLOW	STONE GROUP HOM	IE #2 (SUNNYBROOK	INYBROOK I LLS, ID 834	LANE 104			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIE Y MUST BE PRECEDED BY SC IDENTIFYING INFORMA	FULL ,	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE	(X5) COMPLETE DATE
MM309	Continued From Pa	age 1		MM309			
	K0155 Fire watch failure.	h policy for fire alarm	system	<u> </u>			
	3. K046 Multiple ele	ectrical adapter.	i				
İ							
	•						
j							
ĺ							
			1	 			
Ì							!
							į
I							
							1
STATE FOR	M		D21186	1112 1 + 212-	88\$K21	If continu	ration sheet 2 of 2

p.3

Fire Life Safety Plan of Correction Home #2 Sunnybrook #13G064

corrected faw

K0046

The multiple wiring adapter has been removed. To assure that this deficiency doesn't reoccur a policy will be written regarding multiple adapters and extension cords. Responsible party is Ferren Weeks, Regional Administrator and will be completed by 7/10/2010. All staff will be in serviced on the policy and a copy will be placed in each homes Work Safety Manual. All staff will also be in serviced on the Work Safety Manual, its location in each home, and added to our Employee Orientation Packet. Checking for improper use of these items will be added to the daily night shift cleaning/responsibilities log.

Responsible person will be each Home Administrator to be completed by July 30th 2010

A fire watch policy has been developed and implemented in the event either system becomes inoperable as stated in life safety standards K0154 and K0155. Responsible party is Ferren Weeks, Regional Administrator and will be completed by 7/10/2010.

Currently when either system is in trouble or there is false alarm the maintenance person is to be notified immediately and if the maintenance person is unreachable then the Regional Administrator will be contacted. The maintenance person is to then:

- 1. Notify the Regional Administrator. (If maintenance person is unavailable the Regional Administrator will designate an employee to:)
- Go to the location or direct the home staff how to correct the problem.
- 3. If unable to correct, our contract services will be contacted to correct the problem.
- 4. If unable to correct with in 4 hours then the fire watch policy will be implemented.

A copy of the Fire Watch Policies and Procedures will be provided to the Bureau. All staff will be in serviced on the policy and a copy will be placed in each homes Work Safety Manual. All staff will also be in serviced on the Work Safety Manual, its location in each home, and added to our Employee Orientation Packet.

Responsible person will be each Home Administrator to be completed by July 30th 2010.

K0155- Please refer to K0 154

MM309(1 & 2) Please refer to K0154

MM309 (#3) Please refer to K0046

Reg. admin